

GEOKINETICS INC. minerals exploration and development


280 buchanan field road

• concord, california 94520 •

telephone (415) 676-4462

February 22, 1979

Mr. Ronald W. Daniels
Coordinator of Mined Land Development
Utah Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, UT 84116



Dear Mr. Daniels:

In reference to your letter of February 7, 1979, concerning the Geokinetics Utah Experimental Site #1, we are enclosing a copy of our "Landscape and Erosion Control Plan" prepared by Erik R. Olgeirson Associates.

This report includes the amount and composition of seed mixture recommended by Olgeirson to be used at the site.

We expect to establish pilot revegetation plots on burned-out retorts this fall.

Any comments and suggestions you may have on the enclosed Plan would be greatly appreciated. As you know, revegetation of the surface above a burned-out retort is something new and different, and we expect to do a substantial amount of test work before arriving at the best procedure.

Sincerely,

A handwritten signature in dark ink, appearing to read "Mike Lekas".

MITCHELL A. LEKAS
President

MAL:mfs
Enclosure